-	Work for Property Loc Property is: Single Fam		Duplex		North 2nd Street Other □		
Date:	10/28/2014	illy 🖭	Duples	. 🗀	Other 🗆		
	-	—	ofoty iccurs	. The City	of Milwaukee, the Redevelopment Authorit	hy and their repre	contativos
ake no respo	onsibility for problems discovered a	after the ins	pection da	te, or for on	nissions through error or oversight. The list		
ork required	I by private lenders, insurance cor	npanies, or	by the Fed	deral Block	Grant or HOME programs.		
Exterior	Condition Report						
ocation	Required Work			Note/C	omments		Cost
ite	Landscaping	n/a ☑	Yes 🗌	Self Hel		\$	
	Steps/Handrails	n/a □	Yes 🛂	handra	il @ service steps	\$	124.00
	Service walks	n/a 🗌	Yes 🗸			\$	600.00
	Fencing	n/a ✓	Yes]		\$	
	Parking	n/a ✓	Yes]		\$	
	Retaining walls	n/a ✓	Yes 🗌			\$	
	Other	n/a 🗌	Yes 🗆]		\$	
	Other	n/a □	Yes [\$	
Sarage	Singles: repair	n/a □	Yes 🗆			\$	
	Shingles: Roof over existing	n/a 🗌	Yes [\$	
	Shingles:Tear off & re-roof	n/a 🗌	Yes [\$	
	Gutters/downspouts	n/a 🗌	Yes [\$	
	Flashing	n/a 🗌	Yes 🗌			\$	
	Eaves	n/a □	Yes 🗌			\$	
	Siding	n/a 🗌	Yes [\$	
	Doors	n/a 🗌	Yes _			\$	
	Windows	n/a 🗌	Yes _			\$	
	Slab	n/a 🗌	Yes [\$	
	Paint	n/a 🗌	Yes [\$	
	Electrical	n/a 🗌	Yes [\$	
Porches	Other	n/a □	Yes [\$	
	Roof	n/a ✓	Yes [\$	
	Deck-upper	n/a ✓	Yes 🗌			\$	
	Decklower	n/a ✓	Yes _			\$	
	Steps/handrails	n/a 🗌	Yes 🗸	handra	ils @ both porches	\$	248.00
	Ceiling	n/a ✓	Yes [\$	
	Guardrails	n/a □	Yes 🗸	repair/r	esecure rear porch guardrail	\$	200.00
	Structural	n/a ✓	Yes [\$	
	Doint	n/o	Voc. [/	· 		¢	450.00

n/a 🗌 Yes 🗌

Other

\$

House

Chimney	n/a ☑ Yes 🗌		\$
Shingles: repair	n/a ☑ Yes □		\$
Shingles: Roof over existing	n/a ☑ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑		\$ 8,720.00
Gutters/downspouts	n/a ☐ Yes ☑		\$ 1,008.00
Flashing	n/a ☑ Yes □		\$
Eaves	n/a ☑ Yes □		\$
Siding	n/a ☐ Yes ☑		\$ 200.00
Storm Doors	n/a ☑ Yes □		\$
Prime ("main") Doors	n/a ☑ Yes 🗌		\$ 525.00
Storm Windows	n/a ☑ Yes □		\$
Prime ("main") Windows	n/a ☐ Yes ☑		\$ 250.00
Paint	n/a ☐ Yes ☑ pre	viously painted surfaces	\$ 850.00
Foundation	n/a ☑ Yes 🗌		\$
Electrical	n/a ☑ Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

13,175.00

Interior Co	ondition Report Unit: Entire unit (single family)	✓				Lower unit of duplex		
Mechanical Heating	Upper unit of duplex Required Work					Other		
J	Repair/replace boiler	n/a	V	Yes			\$	
	Repair radiation	n/a	V	Yes			\$	
	Repair/replace furnace	n/a	V	Yes			\$	
	Repair ductwork	n/a	√	Yes			\$	
	Replace thermostat	n/a	√	Yes			\$	
	Repair/replace grilles	n/a	√	Yes			\$	
Electrical	Furnace Venting	n/a		Yes	4		\$	300.00
Electrical	Repair/replace receptacles	n/a		Yes	V		\$	300.00
	Repair/replace switches	n/a		Yes	√		\$	400.00
	Repair/replace fixtures	n/a		Yes	√		\$	475.00
	Install outlets and circuits	n/a	4	Yes			\$	
	Install outlets and circuits	n/a	√	Yes			\$	
	Install outlets and circuits	n/a	√	Yes			\$	
	Install outlets and circuits	n/a	4	Yes			\$	
	Other	n/a		Yes	V	permit	\$	85.00
	Other	n/a		Yes	4	open junction boxes in basement	\$	25.00
Diversións	Other	n/a		Yes	V	loose romex & greenfield wiring in basement	\$	300.00
Plumbing	Repair/replace kitchen sink	n/a	V	Yes			\$	
	Repair/replace kitchen sink fauce	n/a	7	Yes			\$	
	Repair/replace tub	n/a	√	Yes			\$	
	Repair/replace tub faucet	n/a		Yes	√		\$	398.00
	Repair/replace toilet	n/a		Yes	√		\$	298.00
	Repair/replace lavatory	n/a	7	Yes			\$	
	Repair/replace lavatory faucet	n/a		Yes	V		\$	315.00
	Repair/replace wash tub	n/a	✓	Yes			\$	
	Repair/replace wash tub faucet	n/a	√	Yes			\$	
	Unclog piping:	n/a	√	Yes			\$	
	Repair drain/waste/vent piping	n/a		Yes	4		\$	650.00
	Repair water piping	n/a	√	Yes			\$	
					_		•	202.22
	Repair/replace water heater	n/a		Yes	1		\$	800.00

Other n/a Yes \$

Windows											
	Replace broken glass	n/a	4	Yes			\$				
	Repair or replace sash	n/a	7	Yes			\$				
Doors	Repair or replace doors	n/a		Yes	7		\$	950.00			
	Repair or repl. locks/latches	n/a		Yes	V	Self Help	\$	275.00			
Walls/Ceiling	-										
	Repair or repl. @ defective	n/a		Yes	1		\$	300.00			
Paint	Repair or repl. @ defective	n/a		Yes	7		\$	300.00			
Fire Safety											
-	Install smoke/CO alarm:bsmt.	n/a		Yes	√	Self Help	\$	55.00			
	Install smoke/CO alarm: 1st flr.	n/a		Yes	7	Self Help	\$	165.00			
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	110.00			
Handrails	Repair/replace defective	n/a		Yes	V	Self Help	\$	248.00			
Stairs											
Floors	Repair defective	n/a	1	Yes			\$				
110013	Repair defective	n/a	П	Yes	v	including subfloor @ 1st floor bathroom	\$	1,000.00			
Other		n/a		Yes	<u> </u>	NOTE: No Access To 1st Floor Bathroom	\$,			
		n/a		Yes			\$				
		n/a		Yes			\$				
		n/a		Yes			\$				
						Interior: Estimated Cost:	\$	8,049.00			
						Total Exterior and Interior Cost:*	\$	21,224.00			
						*average contracted cost. Actual costs may vary. Self help will reduce	Actual costs may vary. Self help will reduce the amount.				

Inspected by: Tom Frank Date: 10/28/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.